

2

工程决算书

建设单位: 福建省鑫和物业管理有限公司

工程名称: 鑫和·书香苑 1#楼 1T 电梯钢丝绳损坏更换项目

施工单位: 通力电梯有限公司 ✓

预算造价: 壹万零壹佰玖拾捌元整 (¥10198 元)

2021年6月29日

工程（决）算表

工程名称：鑫和·书香苑 1#楼 1T 电梯钢丝绳损坏更换项目

序号	单位估价号	工程或费用名称	计算单位	数量	决算价值		备注
					单价 (元)	合价(元)	
1		10 厘曳引钢丝绳	条	5 条	920	4600	6.82 元/米， 长度 135 米
2		钢丝绳税收 (13%)			598	598	
3		更换人工材料费	台	1 台	4716.98	4716.98	
4		人工费税收 (6%)			283.02	283.02	
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20		合计				10198	含税

和物业



30010002

VATO

力电
限公司

施工单位	通力电梯有限公司 (盖章) 代表 (签字)  		
建设单位	福建省鑫和物业管理有限公司 (盖章) 代表 (签字)  		
证明单位			
业主代表	房号	业主姓名 (手印)	联系电话
	[Redacted]	[Redacted]	[Redacted]
	2	[Redacted]	[Redacted]
	1	[Redacted]	[Redacted]
	[Redacted]	[Redacted]	[Redacted]
	[Redacted]	[Redacted]	[Redacted]
	[Redacted]	[Redacted]	[Redacted]
	[Redacted]	[Redacted]	[Redacted]
	[Redacted]	[Redacted]	[Redacted]
	[Redacted]	[Redacted]	[Redacted]




现场勘察



维修前

维修前




维修前

维修后



维修中

维修中



维修中

维修中



维修中

维修中



维修中

维修中



维修后

维修后



维修后

维修后



维修后

維修后



三
三
三
三

勿
引
斗
三
斗
斗
斗

维修后

维修后.

